



The Standard

PROPELLER LOG

ASA-SP-L

Propeller Record General Information**Propeller Manufacturer** McCAULEY**Model** 1A170 BMS 7660**Hub Series #** NA027**Date of Manufacture** _____**Type** _____**Blade #** _____

Make/Model**Aircraft Installed On:** PIDEN PA-28-181


_____**Serial #**28-2890303

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: 1995	Total Time in Service	Description
Date: Jan. 12	-0-	INSTALLED ON PIPER PA-28-181, S.N. 28-7890303.
Next Inspection	Time Since Overhaul	TACH + TOTAL ON AIRCRAFT. 4635.2 HRS.

March 8, 2024 2588 hours total 7223 hours tach


Cleaned up edges and repainted and reinstalled on Piper PA-28-181, N3474M
I certify that this propeller has been inspected in accordance with
a 100 hr. inspection and was determined to be in airworthy condition.



Allan Hatz
A&P 399782276

July 15, 2025 2602 hours total 7238.2 hours tach

I certify that this propeller has been inspected in accordance with
a 100 hr. inspection and was determined to be in airworthy condition.



Allan Hatz
A&P 399782276

Year: _____

Date: _____

Next Inspection
Due: _____

Year: _____

Date: _____

Next Inspection
Due: _____

Year: _____

Date: _____

Next Inspection
Due: _____