YEAR: DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR: 2001 DATE 6/9	RECORDING TACH TIME
Love	1,200	1 50	636 WES	elw A.D. 80-11-04 BY 1050 DUT PLATES,	6/9	5036.
Four	DO.K.	clw	4.0.0-	1-20-03 BE BY INSDECTION OF TRACKS + ROLLEDS,	1	25 2
FOUNT	DIL. C	1W1	4.0. 16-	07-12 By 095 CHECK OF SWITCH, FOUND 0, K.	e i	
luss.	4005	CHECK	ED ELT		8/10	5040
	<u> </u>					
DATE	3000	1,200	The state of the s			9
. OFFITI	IRS. 5036	IS AIRCR	RAFT HAS BE	 ₽N		
INCDECT	TED IN ACC	ORDANCE	WITH AU	1004		
INSPECT	TION AND V	NDITION.	AAL)			
15a. / 111.	APLAN H	HAT7	(July	Hall	100	
	A & P. 399	782276	Inspection Au	thorization		
			4			
					-	

					· ·
ns of Technician or Repair	YEAR: 2001	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
es,	6/9	5036.4			Junel tires to compensate for wew broke kining good Oforward Rand-Pilot 393-40-6056
ub o.k.		1.000			
0.54	8/10	5040.	6	1	New Battery installed in FLT & tested - OK
					New Batty installed in FLT & tested - OK Replacemed due 09/03 Woward Road - Pilat 393-40-605
		-			
					· · · · · · · · · · · · · · · · · · ·

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE				1 acility. (See back pages for other specific criticos.)
SEPT	. 5, 200	2 500	SO WIZS	2/W A.D. 80-11-04 BY INCT. FOUND O.K. C/W A.D.
87-70-	0'5 27	R4 110	STECT 10	DOF TRACKS + ROLLERS, FOUND O.K. CIW A.D. 76-07-12
	S CHEC			LUGD + TESTED ELT, BATTERY DUE 9 03 . LUSTALLED
- RE	neans o	U man	us. lu	STALLED NEW L-25 BATTERY.
			2.5%	
Table 1	Land Dell	W.S.		
VATE	SEPT	700.07	A CONTRACTOR AND A CONTRACTOR AND A STATE OF THE	autorialists
TACH.	FY THAT T		HRS. <u>5080</u> RAFT HAS E	
	TED IN AC			- CANADA CONTRACTOR CO
	TION AND WORTHY CO			D. B.E.
HA MI	ALLAN		Ille	
	A & P 39		nspection A	thorization

RECORDING YEAR: TACH TIME DATE Oet 1,200 FOUDD BIX POLLERS, F Dov. 2005 DAT AIRWORTHY

POLLERS, FOUND O.K. INSTALLED NEW BP-104	
POLLERS, FOUND O.K. INSTALLED NEW BP-104	CTION OF TRACKS+
12	S ELT BATTERY DUE
Dov. 2005 NST ELT MAIN FAR 91.207 (d).	
TACH. HRS. SAND TOT. HRS. SAND	
I CERTIFY THAT THIS AIRCRAFT HAS BEEN	La
INSPECTED IN ACCORDANCE WITH ANDREAM	
INSPECTION AND WAS DETERMINED TO BE	<u> </u>
IN AIRWORTHY CONDITION A	
ALLAN HATZ CUMP (CA)	
A & P 399782276 Inspection Authorization	

YEAR: 1	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	2004 DATE	TACH
DATE			Eghan Basil	TRANSPONDER CERTIFICATE Airtronics, Inc. 715-823-2161 P.O. Box 297 Clintonville, WI 54929 PERFORMED TRANSPONDER TEST REQUIRED BY FAR 91.413 (a) (c) AND 91.217 (b) IN ACCORDANCE WITH FAR 43 APP. F. Transponder Model King Ki76 A sin Ship Chacled The aircraft and/or component identified hereon was repaired and inspected in accordance with current federal aviation regulations and was found airworthy for return to service. Date 32-04 w.o. 19075 Signed Fase Minimum Properties of the component of	FOUND OPS JUSTA	0.2.6
9/1	5/63.6	2		Date S2-07 w.o. 1701 Signed when signed trus for wear, reported when bravings Inspected broke living - good, Returned to service Alaward Rend, Pilot 393-40-6056		9338 28 01

RECORDING TACH TIME

nician or Repair	YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	12/1/2			es clu	3 E0137 O.Y.
54929 ———————————————————————————————————	026	MECH OF	الدين الم	CH, EOU!	D 9.K. 1051
ced —	VUSTA	LED HE	J 0450	0040-1 50	NONZE BULKHEAD.
				V=	HRS. SILG TOT. HRS. SIEG
		The state of the	20 H	(1)	PAGENTED IN ACCORDANCE WITH ASSOCIATION AND WAS DETERMINED TO BE
		The state of the s			
trus		98 OT 0	MINNES	a v 1966 is <u>Averages Av</u> 196 saas de	ALLAN HATZ A 8 P 399782276 Inspection Authorization

YEAR: DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
JAU.	6,2006	52	26.8 HR 5	a common and a second and and the
de la	clw	3 C.1	0-11-04	BY INSPECTION OF TAIL NUT PLATES, FOUND O.K.
	DUE	53th	urs. clu	A.D. 67-20-03 RZ BY INSPECTION OF TRACKS +
	RULL	三色ら	FOUND ON	DUE 1/2007, CIW A.D. 76-07-12 BY OPS CHECK, DUE 5326 WES
	1050	LLED	NEW DO	-14-5 + B3-5-1 VALUUM FILTERS. JUSTALLED NEW
	BP-1	045 EC	T BATTERY	, bue 2/2008; INSPECTED ELT MAIN FARGLIZOT (d).
				JATE 1806 7006
	1			TACH. HRS. 5276.5 TOT. HRS. 5276.8
		- A	la ma	I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH A
	1	5 v,		INSPECTION AND WAS DETERMINED TO BE
			21. 31 1.3	IN AIRWORTHY CONDITION.
			••	ALLAN HATZ

	YEAR: 2004 DATE	RECORDING TACH TIME
•	2/3/01 	\$ 230,0
	11/19	52694
		9 3 8 3 A A A A A A A A A A A A A A A A A
	es Ate s	San Author

	YEAR:	RECORDING	TODAY'S	TOTAL TIME IN	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repairs must be endorsed with Name, Pating and Certificate Number of Technician or Repairs must be endorsed with Name, Pating and Certificate Number of Technician or Repairs.)
cian or Repair	200 L	TACH TIME	FLIGHT	SERVICE	Facility. (See back pages for other specific entries.)
450	2/3/01	5 230,0	1		Battery replaced
o.v.,				2 PS 7 C 1	installed Gill G-25 SN G02231271.
K5 +	-	We mind	- 20 - 5	100000	Electrical system check - OK
532L was	234	1 - 1 - 2	-	S 1 4 50 1 1 2	Replaced Tail Wheel Tire & reported bearings.
EW	11/19	5269,0)	1.75	Maria proport ()
or (d).		Section (see a real	194 Tel	Section 1990 and 1990	METal AAD 399782276
enec.		HAS' BEEN	HARDELA	SET TART	YHERA
EN		FE OF GAN	IN CHIEF AN	AW GMA K	HT0343M1
BB	1 7	1	E J.HOM	tokoo yuru	A ALEWI
11			12.5	TAH NALL	

YEAR: ———— Date	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
FEB.	1, 200.	า	5244,1	Wite 5
	314	alw	A.D. 80	-11-04 BY INSPECTION OF NUTPLATES FOR CRACKS
	FOUDD	0,4, 7	VE 537	4 HES. CLW A.D. 87-20-03 BZ BY INSPECTION OF TRACKS +
	no Lien.	5, 500	JO 0, K	DUE DELT ADDUCAL, IN S.D. 126-07-12 BY SWITCH OPS CHECK,
	COUDE O.V	· DVE	5374 Has.	DEPECTED ELT YALW FAR GL. 207 (d), ALL O.K. (BAT. DUE ? los).
	LUSTALLED	NEW	מודי טובא	es, 6,00 1 b
	NONSTER		100	TUBES, TACH HRS. 5274.) TOT. HRS. 5274.)
				CERTIFY THAT THIS AIRCRAFT HAS BEEN
	1800000			INSPECTED IN ACCORDANCE WITH ADDICATED TO DE
				INSPECTION AND WAS DETERMINED TO BE
				N AIRWORTHY CONDITION.
				ALLAN HATZ
				& R 399782276 Inspection Authorization

YEAR: RECORDIN

Airtronics, In Clintonville Municip Clintonville, WI 54 Phone (715) 823-2

Customer ______

Model No. _____

Work Performed: _

The Aircraft and with the current ma approved for return If applicable, the

above named oper Aviation Regulation return to service a Pertinent details

Signed

n or Repair	YEAR: RECORDING TODAY'S	TOTAL Descrip	TION OF INCHACTIO	ns, Tests, Repairs and A	Number of Technician or Rep	air
· · · · · · · · · · · · · · · · · · ·		(airframe log)		her specific entries.)		
Trie 1		NTENANCE RELEASE		ner specific entries.)		
		ICEABLE COMPONENT				1100
	Airtronics, Inc		FAA CRS JW5R977M			
-	Clintonville Municipal Airport		12/12/107			_
	Clintonville, WI 54929	Date:	7/13/01			
	Phone (715) 823-2161	_ W.O. No.	20362			
	Customer HOWAND		11.10			
		Mfg.	i re v	and the section is the section of th	The second secon	
-1	Model No. KX 159	Serial No.	71085			
_	Work Performed: REKE	ASKO DICVI	AVIAD	Land Land Carlotte		
	Work Performed.	, chi perje	1 for			
	1F47F11	10 9	PECS			
		//				
	The Aircraft and/or component ide	entified because was renaized and	inapported in accordance			
	with the current maintenance rules of					
	approved for return to service.	The receial Aviation negulation	s, and is all worthly and			
- 1	If applicable, the above identified	aircraft or component was renair	ad as required by the			
	above named operators manual or p					
	— Aviation Regulations under which the					
	return to service as per those requir		and approved for			
	Pertinent details are on file at this		vork order number.			
	Signed					
10.						
horization						
				T		

YEAR: DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR:	RECORDING TACH TIME
MAY	20,20	98	5376	was	MAY	20,200
			REMOU	ED COUT 0-200-A AND INSTALLED LYCOMINE		
	0-300	コーモンド		40366-27 A 1/A/W DEL-AIR STC SA47955W.		INSP. E
			History N 1979	ICH TADMEGS-0-58 HAW DEL AIR STC SATISSUM.		MALW
-	ENCINE	14057	ALLED	USIDE 1-3804-25 MOUNTS TOTER-AN 12550 ALTERNADO		
	VOTER-A	v Rea	uron tov	BELAYALL MAIN DEAWING LIST 15000; INSTALLED		
	SXX-T	ëc 1	49-121	S STARTER DESTALLED PAPER RAZISCE		
	5.W. AZ	9337	VALUUN	Pump. TEST DUO ILAW LIC. SI 1427 B.		
	ALL .	o.L.	LUCTALI	ED NEW ACS A-510-2 SWITCH, A.D. 83-05-06		
	וטק שוסט	EAT	7376 4	NS. IDSTALLED UEW B3-5-1 VACUUM FILTER,		
	66-105	(10:0	er no	HT PAD + 2 1-1944-14 COUL MOUNTS. C/W A.D.	<u> </u>	
	87-20-6	302	34 100	PECTION OF TRACKS + ROLLERS, FOUUD O.L. DUE SATE WAS.		
				cour.		

chnician or Repair	YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	MAY	20, 200	3	5376 V	NEW BP-1045 ELT BLITTERY (DUE 7/2010).
COMINDE			3		2 91.207 (d) JAN O.X. REWIECHED AIRPLANE
MZZPFAA	-	IDSP. E			SEE WT. & BALANCE).
SA 3786 UM.		MAIN	FACE	13.13 C	SEE WY. A BALANCE J.
SA ALTERNANCE		5	-		DATE MAY 20, 2005
NSTALLED					TACH. HRS. 5376 IUI. HRS. BEEN
c			-		THE RESERVE THE PROPERTY OF THE PARTY OF THE
1427 B					INSPECTION AND WAS DEFENDINGED TO
. 93-05-06	191		-		ALRWORTHY CONDITION.
FILTER,					ACLAN HATZ A E P. 399782276 Inspection Authorization
elw A.D.			1	-	
0E 5476 WAS.					

EAR:	RECORDING TACH	TODAY'S FLIGHT	TOTAL TIME IN	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair		Y
					LÌ.	D.
	Duffy's Airc 400 W.29 th Marshfield,	St.		Inc.		Airtronics, I Clintonville Munic Clintonville, WI 5 Phone (715) 823
	June 18, 20 5422.2 Hou		E E	Cessna A150K N8336M 5422.2 Hours Tach s.n. A1500036		Customer /// Model No.
						Work Performed
	Rotated tire due 7/2010		acked bear	ings. Inspected ELT in accordance with FAR 91.207(d), found o.k. (battery		The Aircraft ar
	C/W A.D. 8 C/W A.D. 8	0-11-04 b 7-20-03 R	y inspection	n of nutplates, found o.k., due 5522 hrs. ction of tracks and rollers, found o.k., due at next annual.		approved for refu- If applicable, it above named op
	I certify that			n inspected in accordance with an annual inspection and was determined to		Aviation Regulation return to service Pertinent detail
				Allan Hatz A&P 399782276 Inspection Authorization	_	Signed

Percention of Inspections, Tests, Repairs and Alterations TOTAL Name, Rating and Certificate Number of Technician or Repair Technician or Renair (airframe log) ther specific entries.) MAINTENANCE RELEASE SERVICEABLE COMPONENT Airtronics, Inc FAA CRS JW5R977M Clintonville Municipal Airport Clintonville, WI 54929 Phone (715) 823-2161 Customer HUWAND KAND Model No. KI 70 & b.k. (battery The Aircraft and/or component identified hereon was repaired and inspected in accordance with the current maintenance rules of the Federal Aviation Regulations, and is airworthy and approved for return to service If applicable, the above identified aircraft or component was repaired as required by the above named operators manual or program, and the maintenance rules of the Federal Aviation Regulations under which the operator is certified, and is airworthy and approved for letermined to return to service as per those requirements. Pertinent details are on file at this agency under the above named work order number. Signed

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	· · · · · · · · · · · · · · · · · · ·	pections, Tests, Repairs and A ed with Name, Rating and Certificate		Repair	YEAR:	RECORDII TACH
D/					(ather appoints optrion)	*		D	Duffy's Ai
	Duffy's Air	craft Sales	& Leasing	n Inc			-	_	400 W.29
	400 W.29th	St.	o di Ledolli	j, 111C.					Marshfiel
	Marshfield		19					-	
_		,					_	-	August 1
	July 1, 201	0		Cessna A150K	N8336M				5510 Hou
_	5479 Hour	s Total		5479 Hours Tach	s.n. A1500036		_	_	
							_		
									Installed
	Inspected I	ELT in acc	cordance w	ith FAR 91.207(d), foun	d o.k. (battery due 7/2010).		-		(battery o
									new B3-
	C/W A.D. 8	31-11-04 b	y inspection	on of nutplates, found o.	c., due 5579 hrs.		_		C/W A.D
_	C/W A.D. 8	7-20-03 F	R2 by inspe	ection of tracks and rolle	rs, found o.k. due at next Annua	al inspection.	-		C/W A.D
	C/W A.D. 2	2009-10-0	9 by installi	ing placard and POH ins	sert as required.				hrs
	Loortific the	t this sine	h				-	-	
1	be in airwo	t this airci	an nas bee	en inspected in accordai	nce with an annual inspection a	nd was determined to			I certify t
	De III all WO	itily collui	uon.						be in ain
_					Allan Hatz	Mi del			
					A&P 399782276	he lan			
_		19			Inspection Authorization	n ·	_		
					mapeonon Aumonzand	л			

	1.6					
s Technician or Repa	YEAR:	TACH FLIGHT TIME	Entries must be endors	spections, Tests, Repairs a sed with Name Rating and Corti	and Alterations	r
		Duffy's Aircraft Sales & Leas 400 W.29 th St.	ing, Inc.			1.8
	_ / _	Marshfield, WI 54449				_
	- -	August 12, 2011 5510 Hours Total	Cessna A150K 5510 Hours Tach	N8336M s.n. A1500036		E
		0	•			_
	-1	Installed new BP-1045 ELT (battery due 7/2013). Installed	battery and inspected ELT	in accordance with FAR 91 Plunger and FS-KT-1 strain	.207(d), found o.k. ner gasket kit. Installed	-
	- -	(battery due 7/2013). Installe new B3-5-1 vacuum filter. In	stalled new RA66-105 left	inboard brake pad. Installed	d new BA-6108 air filter.	
	- 4 -	C/W A.D. 81-11-04 by inspe C/W A.D. 2011-10-09 by ins	ection of nutplates, found o.	k., due 5610 hrs.	nnual inspection or 5610	-
uon.		C/W A.D. 2011-10-09 by ins hrs	spection of tracks and roller	s, louid o.k. dao at horas	•	3 -
		I certify that this aircraft has	· · · · · · · · · · · · · · · · · · ·	nee with an annual inspect	ion and was determined to) _
letermined to	-:-	I certify that this aircraft has be in airworthy condition.	been inspected in accorda	lice with an arridar moposi	01/100	_
70	-1-	7.		Allan Hatz A&P 399782276	(display)	POPULATION AND ADDRESS OF THE PARTY OF THE P
	-		*	Inspection Author	rization	-

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR: DATE	RECORDING TACH TIME
DATE		1			A.y.	9 -
	Duffy's Aircra	aft Sales 8	Leasing, I	nc	406	1 6
	400 W.29 th S	St.		—		
-	Marshfield, V	WI D4443			All at	Auc.
	August 23, 2	2012	,	Cessna A150K N8336M —	HACH.	IRS. 55°
	5557 Hours	Total		5557 Hours Tach s.n. A1500036	CERT	FY THAT
		4		h FAR 91.207(d), found o.k. (battery due 7/2013). Installed Rudder stop	LUSPE	TED IN A
-	Inspected E mod Cessna	LT in acco	ordance will	MAA	INSPE	A LIVE AND A STATE OF THE PARTY
					- W AH	WORTHY
	CAM A D 8	1-11-04 by	inspection	of nutplates, found o.k., due 5657 hrs.	1	ALLAN
	C/W A.D. 20	009-10-09	by installin	og Cessna Service Kit SK152-24A.		A A B
	C/W A.D. 20	011-10-09	by inspect	on of tracks, targs and folicies	2	
		this siron	# has hee	n inspected in accordance with an annual inspection and was determined to	_ SZ 970 y	
	be in airwor	this aircid	inn	A. 11		
	be in all wor	try Corion	1011.	Allen Hetz		
				Allan Hatz A&P 399782276	-	
				Inspection Authorization		
_						

nician or Repair	YEAR: DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	Au	9 20	13	5591 was	15 C/W A.D. 2011-10-09 BY 105PECTION OF
	1	4		7	TRACUS, TANUS + ROLLERS, FOUND O.K.
	现心态	Auc.	The state of the s	13	DUE SERI WAS OR DEXT ADDUAL.
	JACH.			HRS. 559 RAFT HAS B	
stop	MSPE	The second of th	Trans.	E WITH A.	
		TION AND WORTHY CO		ERMINED TO	TO BE
		ALLAN	HATZ	Witte	TO THE REAL PROPERTY OF THE PARTY OF THE PAR
113		# & B 39	9782276	Inspection A	Authorizeths.
nined to	***************************************				
_					
-	1				
_					

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
-31	56180	7505	PT / 145	tail while time replaced berning greated
	2000	300	30 25 27 -4	Main gens tires respect - Grandyen
	SAUGE	t 7 k	er pe	re-trends while bearings offend chistil
-355	oredol		1-17	& grussel broke linings good
			1-14	Deward Rand omnit prise 393-40-6056
	Page 1 or safe	2.45		
1311	clo une		lustru	ED NEW BP-1045 ELT BATTERY, DUE 2/2016.
014	7 52			110 Hat at \$ 399782276
				(65
	19.		200	
	-			

Duffy's Aircr 400 W.29th S Marshfield, I

September 5637.4 Ho

Inspected I

C/W A.D. 8 C/W A.D. 2

l certify that be in airwo

cian or Repair	Ϋ́E	Duffy's Aircraft Sales & Leasi 400 W.29 th St.	sing, Inc.	
olari or riopali	-	Marshfield, WI 54449		
2. 1.1	<u>D</u>	September 2, 2014 5637.4 Hours Total	Cessna A150K N8336M 5637.4 Hours Tach s.n. A1500036	
leslal	_	Inspected ELT in accordate pads on right brake.	ance with FAR 91.207(d), found o.k., (Battery due 2/2016). Installed new RA66-105	
-605 L	-	C/W A.D. 2011-10-09 by i	spection of nutplates, found o.k., due 5737 hrs. inspection of tracks, tangs and rollers. found ok, due at 5737 hrs or Sept. 2015	
0-00	-	Loortify that this aircraft h	nas been inspected in accordance with an annual inspection and was determined to	
		Certify that this ancian in	lad book mep	
on per al	_	be in airworthy condition.		
) (b ,	-	be in airworthy condition.	Allan Hatz A&P 399782276	Nhr.
lb.		be in airworthy condition.	Allan Hatz	Nh.
N.b.	-	be in airworthy condition.	Allan Hatz A&P 399782276	Mar.

EAR:	TACH TIME TIME Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or						ian or Repair	lepair	
	Duffy's Aircra 400 W.29 th S Marshfield, V	t.	Leasing, Inc.	any T			-	- -	
	Nov. 28,	Total	5	Cessna A150K	N8336M s.n. A1500036				
4	outer patch p 202T-3 alum MS20470AD	lates at fr inum, tailv rivets as	ont tailwhe wheel attacl	el spring attach point. F h plates made of .065 2	ut 12 from inboard end Rudder and elevator rep 2024T-3 aluminum and	18' up. Installed a 2" by I. Installed new inner an pairs was made using .0; either CR3213, CR3212 accordance with AC 43. on 18 Structural Repair.	nd _ 20 2 or _		
					Allan Hatz	0.1	-		

Allan Hatz A&P 399782276 Inspection Authorization



Duffy's Aircre 400 W.29" S Marshfield, V

October 1, 5675.0 Hou

C/W A.D. 8 C/W A.D. 2

I certify that be in airwor

DORR HILL	-	VEAR	.			pair			
nician or Repai	r —	_	Duffy's Aircraft Sales & Leasing, Inc. 400 W.29 th St. Marshfield, WI 54449						
	-	-	October 1, 2015 5675.0 Hours Total	Cessna A150K 5675.0 Hours Tach	N8336M s.n. A1500036				
	_	-	Inspected ELT in accordance with	n FAR 91.207(d), found o.	k., (Battery due 2/2016).				
٠,	-	-	C/W A.D. 81-11-04 by inspection of nutplates, found o.k., due 5775 hrs.						
by 3"	-	1	the that this aircraft has been	inspected in accordance	with an annual inspection and was determ	nined to			
and .020	-	1	be in airworthy condition.			111 -			
212 or 43.13-1B, pair.	-	_			Allan Hatz A&P 399782276 Inspection Authorization	H _			
11	-								
TATE		/ =	100.00						
1 100	_								

32m.A	December 1, 201			essna A150K	N8336M S/N- A1500036		epair	YEAR:	TACH TIME
	5744.7 Hours To			44.7 Hours Tach	Andrew Control of the		j	DATE	
	Inspected ELT in outboard seat tra	accorda	nce with FAR 9	91.207(d), found o.k.,	(Battery due 01/2019). Installed new MC	0410209-1 pilot			•
	C/W A.D. 2011-1 due at 5844 hour	0-09 by rs or Nov	inspection of tra . 2017		s and installing new pilot outboard seat h		<u> </u>		
	I certify that this	aircraft h	as been inspec	ted in accordance wi	th an annual inspection and was determin	ged to be in			
	airworthy condition	on.			$\bigcap A \cap A$	1			
	× =				Allan Hatz A&P 399782276 Inspection Authoriza		i i		
		hand is	1 1	<u> </u>					
1/	15/18 T	ach	5747.0	Tires rep	And - Deser F	etrent			
			yr a l	Broke Lin	in chekel-OK				
				Wheel begr	in se-probed = DK	i i			
				Nowal &	2000	61313			
				, , , , , ,	4.3		1		

-

	epair	YEAR:	RECORDING TACH		terations Number of Technician or Repair
		DATE	TIME	TRANSPONDER CERTIFICATE Plane Sense Avionics ,715-853-4445 P.O. Box 147	
ot	-			FAA CRS 13PR698Y \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\	
	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1			PERFORMED TRANSPONDER TEST REQUIRED BY FAR 91.413 (a) (c) AND 91.217 (b) IN ACCORDANCE WITH FAR 43 APP. F.	
ok.	<u> </u>			Transponder Model King X+76A s/N 97917	
orc,				The aircraft and/or component identified hereon was repaired and	
				inspected in accordance with current federal aviation regulations and was found airworthy for return to service.	
			3.	Date 6/20/18 W.O. 4533 signed Frankforther	
				Date 6/26/18 W.O. Signed WKM (1000)	
		ļ ——			
	<u> </u>	-	1 5 -		
			r ch		
	, 1-				
		/			

	Duffy's Aircraft Sales & Leasing, Inc. 400 W.29th St.				
	Marshfield, WI 54449		- *	an or Repair	January 5, 2 5762.1 Hour
	November 1, 201	Cessna A150K 5716.0 Hours Tach	N8336M S/N- A1500036		Inspected El tailwheel. In
	Inspected ELT in accordance with Replaced filter BA6108 and filter E		C/W A.D. 20 due at 5862		
	C/W A.D. 81-11-04 by inspection of C/W A.D. 2011-10-09 by inspection		I certify that airworthy con		
	I certify that this aircraft has been i be in airworthy condition.	nspected in accordance wi	th an annual inspection and was determined to		
			Lee Taylor A&P 2702401 Inspection Authorization		
-					
-					
-					
_					

an or Repair	January 5, 2019 5762.1 Hours Total	Cessna A150K 5762.1 Hours Tach	N8336M S/N- A1500036	Re		
	Inspected ELT in accordance tailwheel. Installed new BA-6	with FAR 91.207(d), found o.k., 108 airfilter.	(Battery due 01/2019). Installe	ed new Maule SFSA1-2		
-	C/W A.D. 2011-10-09 by inspudue at 5862 hours or Jan. 202	ection of tracks, tangs and roller 20.	rs and installing new pilot outbo	pard seat rack. Found ok,		
	I certify that this aircraft has b airworthy condition.	een inspected in accordance wi	Allan Hatz	ilistat		
	A&P 399782276 Inspection Authorization					
			A&P 399702276 IIISpection	Authorizatiq		
			AAP 399702270 IIISPECIIOII	Authorizatiqu		
			A&P 399702276 IIISPECIIOII	Authorizatiqu		

CORDING TODAY'S TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	Duffy's i
Duffy's Aircraft Sales & Leasing, Inc.		May 6, 2 5797.1 I
400 W.29 th St. Marshfield, WI 54449		Inspecte
5700 0 11 - 1 1	essna A150K N8336M 8.2 Hours Tach S/N- A1500036	C/W A.D
installed Overnauled airspeed ind. P/N- 28	207(d), found o.k., (Battery due 02/2022) Installed new BA-6108 air filter. 312 S/N-9 see 8130-3 form on file. 5 and Bp-1045. Replaced three instrument panel mounts. Replaced 2 Cowl mount P/N-	I certify t condition
C/W A.D 80-11-04 Nutplate inspVertical	fin attach bracket. Found ok next due 5888 or next annual insp. sks, tangs and rollers and installing new pilot outboard seat rack. Found ok, due at 5888	
I certify that this aircraft has been inspecte condition.	d in accordance with an annual inspection and was determined to be in airworthy	
	Lee Taylor A&P 27024014nspection Authorization	

hnician or Repair	Duffy's Aircraft Sales & Lea	asing, Inc.
A STA	May 6, 2021 5797.1 Hours Total	Cessna A150K N8336M 5788.2 Hours Tach S/N- A1500036
	Inspected ELT in accordan	ice with FAR 91.207(d), found o.k., (Battery due 02/2022) Installed new BA-6108 air filter.
	C/W A.D 80-11-04 by insp C/W A.D. 2011-10-09 by ir	ecting nutplates on vertical fin attach bracket. Found ok next due 5897 or next annual insp. espection of tracks, tangs and rollers and found ok, due at 5897 hours or Feb. 2021.
	I certify that this aircraft ha condition.	s been inspected in accordance with an annual inspection and was determined to be in airworthy
wi mount P/N-		Allan Hatz A&P 399782276 Inspection Authorization
l ok, due at 5888		
ainworthy		
airworthy		
1		

	200 B 10 TO		YEAR:	RECORDING TACH TIME
October 14, 2022 5815.4 Hours Total	Cessna A150K 5806.5 Hours Tach	N8336M S/N- A1500036	DATE	
Inspected ELT in accordance	with FAR 91.207(d), found o.k., (Ba	ttery due 08/2024).		
	16 -Hh h	racket. Found ok next due 5915 or next annual insp. ad found ok, due at 5915 hours or October 2023.		
Penlaced right nav light with	Norman Lamp NLI-7512-12.		and to	
I certify that this aircraft engir	ne and propeller have been inspecte	d in accordance with an annual inspection and were determi	ned to	
be in airworthy condition.	Jus	tin Smith 2742439 Dection Authorization		
	III5	Section Additions		